DART SERVICE INSTRUCTION

To further protect Dart crosstubes from mechanical damage in service, they may be treated with "Armor Shield" surface treatment. To designate crosstubes with 'Armor Shield' add 'A" to the Part Number. For example, D206-667-101A is a D206-667-101 crosstube coated with Armor Shield. It is acceptable to apply the Armor Shield in regions shown in Figure 1 or Figure 2 only. It is **NOT** acceptable to apply Armor Shield in the cuff and support/clamp regions. The following installations are applicable:

INSTALLATION	STC		CURRENT
INSTALLATION	CANADIAN	FAA	CHANGE NUMBER
D205-596-101A/-103A/-105A/-107A	SH03-6 ISSUE 3	SR01742NY	CHG 002 (or later)
D212-664-101A/-201A		3 SR01298NY	CHG 003 (or later)
D412-664-203A	SH01-9 ISSUE 3		CHG 005 (or later)
D212-664-107A/-207A	3001-91330E3		CHG 001 (or later)
D412-664-105A/-205A/-209A			CHG 001 (or later)
D206-667-101A/-103A/-201A/-203A	SH01-5 ISSUE 3	SR01304NY	CHG 002 (or later)
D407-667-105A/-205A	3HU1-3 133UE 3		CHG 003 (or later)
D058-676-101A/-201A	N/A	SR01018SE	CHG 002 (or later)
D350-748-101A/-201A	SH06-27 ISSUE 1	SR02359NY	CHG 001 (or later)

1.0 TO APPLY ARMOR SHIELD

- 1.1 Ensure the crosstube is appropriately finished in accordance with the relevant manufacturing drawing or Instruction for Continued Airworthiness (ICA).
- 1.2 Clean/degrease surface of crosstube using Methyl Ethyl Ketone (MEK), 4105S Wash'n'Wipe Degreaser, or equivalent and wipe the surface to clean the entire area
- 1.3 Mask areas around supports and cuffs per Figure 1 or Figure 2 (D350-748-101/-201 only). Abrade paint finish in areas requiring protection using 800 grit sandpaper. Ensure the surface is de-glossed.
- 1.4 Re-clean the surface per Step 1.2.
- 1.5 Mix BCG4 Component A and BCG4 Component B in accordance with manufacturer's instructions.
- 1.6 Apply 5 wet coats in accordance with manufacturer's instructions.
- 1.7 To avoid hard tape line, unmask immediately after application of last coat.
- 1.8 Allow BCG4 to dry in accordance with manufacturer's instructions.

2.0 ARMOR SHIELD REMOVAL / RE-APPLICATION

To remove the Armor Shield coating or if damage to the coating and/or crosstube is observed during inspection.

- 2.1 Remove Armor Shield from the affected area using 80 grit sandpaper. To remove Armor Shield from larger areas, bead blasting has been determined to be the most effective technique.
- 2.2 Repair mechanical damage (within limits) to the crosstube and touch up finish in accordance with the relevant ICA.
- 2.3 Apply Armor Shield in accordance with Section 1.0 of these instructions.
 - * Note that crosstubes with a change number prior to those listed in the above table used a Proform PF746/746-1 treatment, which has been discontinued. The current BCG4 treatment should be used for any re-application of the armor coat. The two treatments have a different surface texture and, at the operator's discretion, it may be preferential to completely re-finish the crosstube rather than touch up the discontinued armor coating.

CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-0-01			
BY: D. SHEPHERD (DE # 02)			
DATE:			

В	BCG4 REPLACES DISCONTINUED PROFORM PF 746 OR PF 746-1; ADD D350-748-101/-201			МВ	07.10.17
Α	A NEW ISSUE		PH	06.02.14	
REV.	DESCRIPTION		BY	DATE	
DESIGN		PH	DART AEROSPACE LTD		LTD
DRAWN		P	HAWKESBURY, ONTARIO, CANADA		
CHECKE	ĒD	LE	DRAWING NO.		REV. C
MFG. AF	PR.	N/A	DSI 9326		SHEET 1 OF 2
APPRO\	/ED	19	TITLE		SCALE
DE APPI	R.	-#	ARMOR SHIELD		NTS
DATE	08.0	1.08	COPYRIGHT © 2006 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATION TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.		

08.01.08

ADD D212-664-107A/-207A & D412-664-209A, REWRITE




FIGURE 1 - ACCEPTABLE REGIONS TO BE COATED WITH ARMOR SHIELD (SEE FIGURE 2 FOR D350-748-101/-201 CROSSTUBES)




FIGURE 2 - ACCEPTABLE REGIONS TO BE COATED WITH ARMOR SHIELD (D350-748-101/-201 ONLY)

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

APPROVED

BY:
D. SHEPHERD (DE # 02)

DATE:
CERT. NO.:
SEE TABLE
ISSUE NO.:
SEE TABLE

DESIGN	PH	DART AEROS	PACE LTD
DRAWN	(q)	HAWKESBURY, ONTARIO, CANADA	
CHECKED	LE	DRAWING NO.	REV. C
MFG. APPR.	N/A	DSI 9326	SHEET 2 OF 2
APPROVED	140	TITLE	SCALE
DE APPR.	#	ARMOR SHIELD	NTS
DATE 08.0	1.08	COPYRIGHT © 2006 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	